



TECHNICAL DATA SHEET

2006 Page 1 of 2

2006

CHLOROBUTYL WITHOUT TIE GUM

October 1, 2009

Polycorp 2006 is a 50A durometer "Pure" black chlorobutyl rubber lining. Excellent chemical resistance at elevated temperature. Superior lining to handle strong sodium hypochlorite solution up to 15% available chlorine. Suitable for 70% hydrofluoric acid service.

Application Notes:

- **Skive** use skive-butt joint covered with 2007capstrip (4" wide x1/8" thick)
- Repair Same
- **Cured Durometer** Shore A Durometer of top surface: 50 ± 5.
- A heated table to warm the rubber to 110– 120°F (43°C) is recommended
- **Spark Test** Refer to section 13 of the Application Manual

Adhesive Notes:

See Section 9 of the Polycorp Rubber Lining Application Manual for specific cementing / adhesion notes.

For proper adhesion, temperatures must be over 60°F (15°C) and must not exceed 120°F (49°C). Use adhesives in well ventilated area and always consult the material safety data sheet for specific precautions.

<u>Coat</u>	Polycorp Adhesive	<u>Approved</u> Equivalent
1 st Coat on	C-100	Chemlok
Metal	Primer	205
2 nd Coat on	C-101	Chemlok
Metal	Intermediate	252X
3 rd Coat on	CB Tack	CB Tack
Metal		
4 th Coat on	CB Tack	CB Tack
lining		

For distributors of Chemlok adhesives, see Section 9 of the Application Manual

Curing:

Cure time adjustments may be required to compensate for specific conditions. See Section 11 of the Application Manual for detailed instructions.

Autoclave Method – Up to 1/4" thickness: 1 $\frac{1}{2}$ hours @ 292°F/144°C (45 psi).

Internal Steam Method – Up to 1/4" thickness:

10 hours @ $274^{\circ}F/134^{\circ}C$ (30 psi); or 20 hours @ $260^{\circ}F/127^{\circ}C$ (20 psi).

Atmospheric Steam Method – Up to 1/4" thickness:

Minimum 50 hours @ 212°F/100°C.

Storage:

Store in a cool, dry area.

Shelf Life:

Stored below 50°F (10°C)	180 days	
Stored between 51 and 70°F	60 days	
Stored between 71 and 90°F	30 days	
Do not store above 90°F (32°C)		

Storage, handling and application methods must conform to the Polycorp Rubber Lining Application Manual





TECHNICAL DATA SHEET

2006 Page 2 of 2

Typical Properties:

Property	<u>Value</u>	ASTM Test Method
Hardness (Face)	50 A ± 5	D2240
Tensile Strength (min, psi)	1200	D412
Elongation at Break (min, %)	400 %	D412
Specific Gravity	1.21	D927
Adhesion to Metal (min, lbs)	25	D429
Maximum Operating Temperature for Optimum Service Life	104°C/ 220°F	N/A

All physical property values developed and measured using a press-cured sample sheet prepared in accordance with ASTM D3182.

PRECAUTIONS:

- Joints can be made using either a lap or skive-butt construction. Skive-butt joint should be covered with a cap strip (4 "wide x 1/8" thick) of plain chlorobutyl 2007.
- Swab mating surfaces of cap strip and lining with toluol solvent. **Do not use cement on cap strips.**
- Preheat cap strip for at least 10 minutes on a 120°F/43°C heat table. Thoroughly stitch edges of cap strip so edges are completely sealed.